
Web Images Videos Maps News Shopping Gmail more ▼



Sort by relevance | Sort by date (new first) | Sort by date (old first)

Method of operating a

wireless and a short-range wireless connection in the ...

US Pat. 6326926 - Filed May 18, 2000 - Telxon Corporation

The stationary terminal 70 also includes a **display** 72, a keyboard 74 and a ...
The hand held portable device 100 is protected by battery power **failure** by a ...

Link connection method between communication terminals equipped with ...

US Pat. 7046961 - Filed Aug 10, 2001 - Samsung Electronics Co., Ltd.

The automatic link connection attempt number set by Bluetooth wireless ...

indicating the link ${f connection}$ failure, and ends the link ${f connection}$ procedure.

Telephone station equipment employing rewriteable display keys

US Pat. 5917905 - Filed Feb 14, 1997 - Intrinsic Solutions. Inc.

Failure of the PC is 15 detected by the expansion board, ... a PC or other desk-

top work station that is connected to a wired or wireless telephone system. ...

Repair and maintenance support system and a car corresponding to the system

US Pat. 6438471 - Filed Oct 12, 2001 - Hitachi, Ltd.

9 shows the elements constituting the failure reception table relating to the

... through a wireless connection is installed in the navigation apparatus 3.

Docking system for establishing secure wireless connection between computer ...

US Pat. 6072468 - Filed Apr 10, 1997 - International Business Machines Corporation

An advantage of having docking port 83 physically attached to ${\it display}$ means \dots

then a user acknowledgement (108) is provided to signal docking failure and ...

Docking method for establishing secure wireless connection between computer ...

US Pat. 5923757 - Filed Apr 10, 1997 - International Business Machines Corporation

An advantage of having docking port 83 physically attached to **display** means ... then a user acknowledgement (108) is provided to signal docking **failure** and ...

Repair and maintenance support system and a car corresponding to the system

US Pat. 6549833 - Filed Aug 9, 2002 - Hitachi, Ltd.

9 shows the elements constituting the failure reception table relating to the

... through a wireless connection is installed in the navigation apparatus 3.

Docking system with docking port for establishing secure wireless connection ...

US Pat. 6067076 - Filed Apr 10, 1997 - International Business Machines Corporation

An advantage of having docking port 83 physically attached to **display** means ... then a user acknowledgement (108) is provided to signal docking **failure** and ...

Docking method for establishing secure wireless connection between computer ...

US Pat. 5930368 - Filed Apr 10, 1997 - International Business Machines Corporation

An advantage of having docking port 83 physically attached to **display** means ... then a user acknowledgement (108) is provided to signal docking **failure** and ...

Method and apparatus for opening a virtual serial communications port for ...

US Pat. 7043205 - Filed Sep 11, 2001 - 3Com Corporation

In addition, for purposes of opening a VCOM port, the connection manager

coordinates communication between the wireless communication protocol stack (eg,

The Stay up to date on these results using the patents RSS feed on wireless connection failure display.



wireless connection failure display

itrage. • E 2 I 2 2 L 2 2 IS

Search Patents

Google Home - About Google - About Google Patents - Google Patents Help

@2009 Google

Advanced Patent Search